

**SECRET
IDEALIST**

IDEA-2776-65

Copy 5 of 5

5 October 65

MEMORANDUM FOR : Deputy for Field Activities, OSA

**SUBJECT : [] Commander's Report
August 1965**

25X1

Reference Paragraph VI, B. 1: Corrective action has been taken to insure proper operation of the [] even though the pilot turns the control switch to Mode IV which is normally an unused switch position when used with the [].

25X1

25X1

SIGNED

[]
**Sensor Systems Division
(Special Activities)**

25X1

SSD/OSA [] :pca (5 Oct 65)

25X1

Distribution:

- 1 - D/FA/OSA
- 2 - D/TECH/OSA
- 3 - SSD/OSA
- 4 - D/TECH/OSA (Chrono)
- 5 - RB/OSA

**IDEALIST
SECRET**

GROUP 1
Excluded from automatic
downgrading and
declassification

25 YEAR RE-REVIEW